

WEST

[Generate Collection](#)*Search Results - Record(s) 16 through 16 of 16 returned.* 16. Document ID: US 4748511 A

L1: Entry 16 of 16

File: USPT

May 31, 1988

DOCUMENT-IDENTIFIER: US 4748511 A
TITLE: Teleradiology system

388/433

DEPR:

The modem dials the number and tries to establish a link. If the line is busy or a similar problem occurs, the modem will immediately re-dial the number three times before giving up. If a link still cannot be established, the modem posts a message to the CPU, which prints an "idle" message on line 5 of the call menu (if it is displayed) and all of the tagged images are marked with a "not sent". The user must initiate the call again before transmission can be achieved.

[Full](#) | [Title](#) | [Citation](#) | [Front](#) | [Review](#) | [Classification](#) | [Date](#) | [Reference](#) | [Claims](#) | [KWIC](#) | [Draw Desc](#) | [Image](#)[Generate Collection](#)

Terms	Documents
<i>immediately redial\$ or immediately re-dial\$</i>	16

[Display](#)

15

Documents, starting with Document:

16

Display Format:[KWIC](#)[Change Format](#)